


NOTICE - CHANGES IN 8276 SERIES 1" INSULATED END PIECE


With this shipment please be aware that there has been a change in the insulated end piece of the 8276 Series 1" valve. This new end piece is completely interchangeable with any 8276 1" valve.



3/22 800-292-2737 | sales@aymcdonald.com | aymcdonald.com 3210-447

NOTICE - CHANGES IN 8276 SERIES 1" INSULATED END PIECE


With this shipment please be aware that there has been a change in the insulated end piece of the 8276 Series 1" valve. This new end piece is completely interchangeable with any 8276 1" valve.



3/22 800-292-2737 | sales@aymcdonald.com | aymcdonald.com 3210-447

NOTICE - CHANGES IN 8276 SERIES 1" INSULATED END PIECE


With this shipment please be aware that there has been a change in the insulated end piece of the 8276 Series 1" valve. This new end piece is completely interchangeable with any 8276 1" valve.



3/22 800-292-2737 | sales@aymcdonald.com | aymcdonald.com 3210-447

NOTICE - CHANGES IN 8276 SERIES 1" INSULATED END PIECE

With this shipment please be aware that there has been a change in the insulated end piece of the 8276 Series 1" valve. This new end piece is completely interchangeable with any 8276 1" valve.



3/22 800-292-2737 | sales@aymcdonald.com | aymcdonald.com 3210-447